



10 YEAR PUNCTURE RESISTANCE WARRANTY SHIELDIT™ - NEW CONSTRUCTION

Dryvit Systems, Inc. ("Dryvit") hereby warrants in the limited manner specified herein that the ShieldIt base coats manufactured and sold by Dryvit shall be free from defects in the manufacture of the materials. For a period of ten (10) years from the date of substantial completion of the project, when installed in accordance with Dryvit's current published literature as a component of a new Dryvit Outsulation® system, the ShieldIt base coats will not be punctured by woodpeckers.

ShieldIt 1st Coat (Grey) and ShieldIt 2nd Coat (White) are installed as a component of an Outsulation® system, which includes the air/water-resistive barrier, insulation board, adhesive and basecoat, reinforcing mesh and textured acrylic finish.

The sole responsibility and liability of Dryvit under this warranty shall be to provide the labor and materials necessary to repair or replace the areas of ShieldIt base coats and textured acrylic finish that have been punctured. Dryvit will determine in its sole discretion the appropriate scope and method of repair or replacement to remedy any condition covered by this warranty.

This warranty does not cover ShieldIt base coats or textured acrylic finish installed by an applicator or contractor firm that has not completed a Dryvit system training program or ShieldIt base coats or textured acrylic finish that have not been paid for in full. This warranty does not cover materials produced by other manufacturers not bearing Dryvit's name or logo or materials not sold by Dryvit, its authorized distributors or licensed board suppliers, even if such materials bear Dryvit's name or logo. This warranty does not cover cracking. This warranty does not cover any sealant materials. This warranty is void if the ShieldIt base coats are intermixed with other chemicals or materials not specifically required by Dryvit's published technical literature. This warranty does not cover any damage caused by architecture, engineering, insufficient or defective waterproofing, any damage caused by improper workmanship, any damage caused by direct vehicular contact or natural or accidental phenomenon, including but not limited to lightning, hailstorms, floods, hurricane force winds, tornadoes, earthquakes, fire, falling objects, or chemicals. Any repair, restoration or replacement of the ShieldIt base coats or textured acrylic finish related to the above referenced items will be at the owner's expense.

Except as modified herein, all terms, conditions and limitations contained in the Outsulation® system warranty shall apply.